

L Number	Hits	Search Text	DB	Time stamp
1	0	"10607022"	USPAT	2004/08/19 15:46
2	0	"10607022"	USPAT;	2004/08/19 15:47
3	1	"10/607022"	USPAT;	2004/08/19 15:50
4	1	6330986.pn.	USPAT;	2004/08/19 15:50
29	8	("4021008"   "4036457"   "4277672"   "4386749"   "4514619"   "6137082"   "6194685"   "6237874").PN.	USPAT	2004/08/19 16:29
-	207	244/134r,134b.cccls. and (temperature heat heating heater)	USPAT	2004/08/17 13:20
-	211	244/134r,134b.cccls. and (temperature heat heating heater)	USPAT	2004/08/17 13:20
-	75	244/134r,134b.cccls. and resistance	USPAT	2004/08/17 14:20
-	31	244/134r,134b.cccls. and (resistance near3 (temperature heat heating heater))	USPAT	2004/08/17 13:21
-	47	("2106323"   "2167972"   "2406367"   "2454874"   "2464273"   "2590944"   "2665090"   "2686640"   "2757273"   "2787694"   "2791668"   "3002718"   "3013752"   "3178560"   "3397302"   "3404061"   "3420476"   "3553834"   "3719608"   "3748522"   "4021008"   "4036457"   "4181583"   "4250397"   "4282184"   "4457491"   "4490828"   "4659421"   "4737618"   "4808481"   "4942078"   "4972197"   "5022612"   "5100737"   "5165859"   "5192605"   "5198063"   "5248116"   "5344696"   "5449134"   "5475204"   "5544845"   "5584450"   "5629559"   "5657951"   "5934617"   "5947418").PN.	USPAT	2004/08/17 13:50
-	82	244/134r,134b.cccls. and (resistance resistive resistor)	USPAT	2004/08/17 14:20
-	75	244/134r,134b.cccls. and (resistance resistive resistor) and (temperature heat heater heating)	USPAT	2004/08/17 15:41
-	10	244/134r,134b.cccls. and ((resistance resistive resistor) with (detect\$4 measu\$5 sens\$5))	USPAT	2004/08/19 12:31
-	212	324/720-721.cccls.	USPAT	2004/08/17 15:40
-	104	324/720-721.cccls. and (resistance resistive resistor) and (temperature heat heater heating)	USPAT	2004/08/17 15:41
-	113	244/134r,134b.cccls. and (separate disconnect separated disconnected failed)	USPAT	2004/08/17 15:47
-	10	244/134r,134b.cccls. and ((detect\$4 sens\$5 determin\$4) with (separate disconnect separated disconnected failed fail))	USPAT	2004/08/17 15:56
-	26	244/134r,134b.cccls. and (fail)	USPAT	2004/08/17 16:18
-	976	244/134r,134a,134b,134c,134d,134e,134f.cccls	USPAT	2004/08/18 08:23
-	13	244/134r,134a,134b,134c,134d,134e,134f.cccls and ((sens\$5 detect\$5 determin\$4) with (fail failure))	USPAT	2004/08/17 16:32
-	1	6330986.pn.	USPAT	2004/08/17 16:37
-	1	6129314.pn.	USPAT	2004/08/17 16:37
-	976	244/134r,134a,134b,134c,134d,134e,134f.cccls	USPAT	2004/08/18 08:23
-	0	244/134r,134a,134b,134c,134d,134e,134f.cccls and (heater with (high adj2 (resistance resistivity)))	USPAT	2004/08/18 08:28
-	0	244/134r,134a,134b,134c,134d,134e,134f.cccls and (heater with (high adj3 (resistance resistivity)))	USPAT	2004/08/18 08:28
-	2328	(nickel adj alloy) and (high adj3 (resistance resistivity))	USPAT	2004/08/18 08:39
-	145	(nickel adj alloy) with (high adj3 (resistance resistivity))	USPAT	2004/08/18 12:41
-	500	aircraft and (flap with separat\$4)	USPAT	2004/08/18 08:47
-	22	aircraft and ((flap with separat\$4) with (sens\$4 detect\$4 determin\$5))	USPAT	2004/08/18 09:21

-		7	244/134r,134a,134b,134c,134d,134e,134f.cccls and delamina\$5	USPAT	2004/08/18 09:22
-		5	("4060212"   "5061836"   "5615849"   "5623821"   "6489915").PN.	USPAT	2004/08/18 09:29
-		22108	delamina\$5	USPAT	2004/08/18 10:06
-		1478	delamina\$5 and (aircraft airplane)	USPAT	2004/08/18 10:07
-		301	delamina\$5 and (aircraft airplane) and (delamina\$5 with (temperature resistance))	USPAT	2004/08/18 10:12
-		82	244/134r,134a,134b,134c,134d,134e,134f.cccls and ((delamina\$5 separat\$5 disconnect\$4) with (surface))	USPAT	2004/08/18 10:18
-		35	244/134r,134a,134b,134c,134d,134e,134f.cccls and ((delamina\$5 separat\$5 disconnect\$4) with (detect\$4 sens\$5 determin\$5))	USPAT; US-PPGPUB	2004/08/18 10:22
-		29	244/134r,134a,134b,134c,134d,134e,134f.cccls and ((delamina\$5 separat\$5 disconnect\$4) with (temperature resistance))	USPAT; US-PPGPUB	2004/08/18 10:43
-		835	324/715-718,720-721.cccls.	USPAT; US-PPGPUB	2004/08/18 10:44
-		24	324/715-718,720-721.cccls. and (airplane aircraft)	USPAT; US-PPGPUB	2004/08/18 10:55
-		16	("2599059"   "2627012"   "3022412"   "4561613"   "4747575"   "4826108"   "4875644"   "5098037"   "5129598"   "5152480"   "5427332"   "5562265"   "5657951"   "5657952"   "5904322"   "5921502").PN.	USPAT	2004/08/18 11:56
-		128	(nickel adj alloy) with (high adj2 (resistance resistivity))	USPAT	2004/08/18 12:41
-		5	(nickel adj alloy) with (high adj2 (resistance resistivity)) and (airplane aircraft)	USPAT	2004/08/18 12:41
-		1	6330986.pn.	USPAT	2004/08/18 14:56
-		41	244/134r,134b,134a,134c,134d,134e,134f.cccls and ((resistance resistive resistor) with (detect\$4 measu\$5 sens\$5))	USPAT	2004/08/19 12:39
-		2	("6607354" "6753513").pn.	USPAT	2004/08/19 12:40
-		8	("4021008"   "4036457"   "4277672"   "4386749"   "4514619"   "6137082"   "6194685"   "6237874").PN.	USPAT	2004/08/19 12:41
-		494	244/134r,134b.cccls.	USPAT	2004/08/19 15:46